•	Approved For Release 2000/05/18 : CIA-RDP82-00457R004100570008-0 CLASSIFICATION CLASSIFICATION OF CONTROL OF THE CONTROL OF T
COUNTRY	
	Soviet Zone of Garmany REPORT NO.
TOPIC	Tank Repair Shop in the EBERSWALDE Eisenspalterei
1 X	
EVALUATION_	PLACE OBTAINED 25X1A
(1A DATE OF CO	
(1A DATE OBTAIN	DATE PREPARED 20 December 1949
	1 ENCLOSURES (No. & TYPE)
	DETUDAL TO CLA LIBRARY
an antigrad lighter-appear - spelor even manufacture en-e-e-e-e-e-e	RETURN TO CIA LIBRARY
an an managar (Managara) and an analysis of the same and a	
25X1X	The second secon
SOURCE	
5	shop on the premises of the Eisenspalterei (iron works) factory area, EBERSWALDE (N 53/V 08), early in the morning. The factory is east of the HBERSWALDE-LICHTERFELDE (N 53/V 09)
	road and south of Hohonzollern Canal. The tank repair shop occupies the damaged southern factory building (about 500 x 16 feet). The three other factory buildings were destroyed during the war.
25X1C	occupies the damaged southern factory building (about 500 x 16
25X1C	occupies the damaged southern factory building (about 500 x 16 feet). The three other factory buildings were destroyed dur-
25X1C	occupies the damaged southern factory building (about 500 x 16 feet). The three other factory buildings were destroyed dur-
25X1C	occupies the damaged southern factory building (about 500 x 16 feet). The three other factory buildings were destroyed dur-
25X1C	occupies the damaged southern factory building (about 500 x 16 feet). The three other factory buildings were destroyed dur-
25X1C	occupies the damaged southern factory building (about 500 x 16 feet). The three other factory buildings were destroyed dur-
25X1C	occupies the damaged southern factory building (about 500 x 16 feet). The three other factory buildings were destroyed dur-
25X1C	occupies the damaged southern factory building (about 500 x 16 feet). The three other factory buildings were destroyed dur-

CLASSIFICATION

CONTROL/US OFFICIALS ONLY